
Louisville Metro Land Development & Transportation Committee – January 13, 2022, Continued from December 9, 2021 Virtual Neighborhood Meeting – July 15, 2021

DOCKET NO. 21-ZONE-0104

ZONE CHANGE FROM R-4 TO R-7 TO ALLOW A 174-UNIT MULTI-FAMILY DEVELOPMENT ON PROPERTY LOCATED AT 10410 & 10414 OLD PRESTON HIGHWAY



Attorneys: Bardenwerper Talbott & Roberts, PLLC Land Planners, Landscape Architects, & Engineers: Mindel Scott & Associates, Inc.









Maple Spring Drive Intersection Bethany United Church of Christ SITE Old Preston Hwy ple Spring Dr


Looking south down Preston Hwy at Maple Spring Drive access to Old Preston Hwy.



Looking south from Maple Spring Drive down Old Preston Hwy.




Looking north at entrance to Old Preston Hwy. from Preston Hwy and Interchange Drive.




Looking north down Old Preston Hwy Interchange Drive.




Looking north down Old Preston Hwy heading towards site. Okolona Fire Department to the left.




Commerce Crossing Intersection Old Presion Highway Presson Highway Connensing Seossing Drive Coxes Preston Highway Coulding Less Chopsilis Diving Old Preston Highway



Adjacent properties south and north of site







Karst and Geotechnical Engineering Study

GEOTECHNICAL ENGINEERING STUDY

PROPOSED APARTMENTS 10410 OLD PRESTON HIGHWAY LOUISVILLE, KENTUCKY

ASHER PROJECT No. 21-077

Prepared For:

Mr. Brent Hackworth brent@highgates.com

Prepared By:

Asher Engineering, Inc. 1021 South Floyd Street Louisville, Kentucky 40203

July 13, 2021

January 15, 2022 Karst Update

Asher Engineering, Inc.

Environmental & Engineering Consulting

January 15, 2022

Mr. Brent Hackworth brent@highgates.com

Proposed Old Preston Highway Apartments 10410 and 10414 Old Preston Hwy

On January 15, 2022 Asher Engineering visited the referenced site to interview the residents and inspect the backyards of seven neighboring properties for possible karst activity and sinkholes. The properties visited were: 4600, 4602, 4604, and 4606 Walden Dr., and 10310, 10400, 10412 Old Preston Highway. We spoke with residents at 4600, 4604, and 4606 Walden Drive. No one was available for interview at the other properties at the time of our site visit.

Inspection of the depressed areas at the neighboring properties confirmed these areas are indeed sinkholes. We noted that the sinkholes at the backyards at 4602, 4604, and 4606 Walden Drive, and the sinkholes at 10310 and 10400 Old Preston Highway extend into the subject site. We also noted a sinkhole on the subject site just south of 4602 Walden Drive.

Sinkholes are formed by the dissolution of the underlying limestone bedrock. Depressions in the ground surface can develop when bedrock surfaces dissolve over years of water migrating thru the area. The dissolved rock may leave a void space, or the void may be replaced by soft redeposited soil. Over time, the weight of the soil subsides over the void or soft soil, leaving a visible depression in the ground surface. A review of geographic maps revealed that the site is underlain by the Louisville Limestone formation. This formation is susceptible to karst activity and sinkhole formation.

The subject property is suitable for development with the apartment buildings and pavement areas, provided the site is inspected by a geotechnical engineer during the sitework, bldg, and road construction. This inspection would include a visual observation of the soil subgrade after the site has been stripped of grass and topsoil. A prooffoll with a loaded dump truck would be conducted to identify any soft areas in the soil subgrade. Test pits with a backhoe or excavator may also be conducted to inspect any soft subgrade areas identified by the visual inspection and prooffoll. If depressed areas and/or sinkholes are identified at the time of the construction inspection, recommendations for stabilizing the sinkholes would be provided on site. While there is some variation in the methods to stabilize sinkholes, the repair would generally be as follows: The sinkhole area would be cleaned of all soft soil down to bedrock.

The excavation would be draped with a nonwoven geotextile fabric in the bottom and sides, and the area backfilled with crushed limestone. The geotextile fabric would then be placed over the crushed limestone, and the area backfilled with compacted soil up to finish grade. Any sinkholes that extend over property lines must be repaired on both properties to insure complete stabilization of the sinkhole area.

The Highgates Group has retained Asher Engineering to provide Construction Testing and Inspection during the sitework and building construction for the project. In addition to our normal inspections, we will include monitoring of the adjacent properties to confirm that the construction activities are not impacting the neighboring sites.

Sincerely.


Pullih

Richard A. Linker, P.E.

RICHARD A LINKER 16420 CONTACT CONTACT

1021 S. Floyd Street • Louisville, Kentucky 40203 • Office: (502) 589-0073 asherinc@a01.20

Access provided to the Hassler property



Okolona Fire Dept approving the access provided to the Hassler property



OKOLONA FIRE PROTECTION DISTRICT

Mark S. Little, Fire Chief 8501 Preston Highway Louisville, Kentucky 40219 Phone (502) 964-5111 Fax (502) 965-8388 www.okolousfire.org

o: Allison Hicks -Mindel Scott


From: Major Frankie Nalley

Date: 1/21/2022


RE: 10410 and 10414 Old Preston Hwy

After meeting at the site today and seeing the proposed site plan for the apartments going in at 10410 and 10414 Old Preston Hwy. The Okolona Fire Department is good with the plans showing the access for 10412 Old Preston Hwy property connecting into the apartment complex. No separate access is needed for the address of 10412 Preston Hwy.

Fire Marshal Major Frankie Nalley




I bdrm - front elevation




I bdrm - side elevation


I bdrm - side elevation



Type B - south elevation




Type B - north elevation



Type B - west elevation

Type B - east elevation




AGENTAGE I CHANGOLE ROYOF NAME THE PROPER WORLD.

FOR THE PROPER WORLD. EMPLEMENT CONTRACTOR
C LEVEL 4 4 tEVEL 2 SPECT LAP DIDBED - REHTY MINER VENERAL LAN LEVELT S

Address t bereits & Rock

2 bdrm - back elevation

MANCO TOKOWO HEAD





2 bdrm - east elevation

2 bdrm - west elevation




Type D - front elevation





Type D - right elevation



LÉVÉL 4 4 1307 8 4 A CRIMANA GUARGINA VISENCA ASSIGUARA

LEVEL 3 **
121 - 5"
WHIS DATTH SCHOOL
ACCEPT
WHIT LAP SCHOOL MARTS

LEVEL 2


ENCE ROBIOCH
WATER VAN
ENVEL 1
1007 - 07
T O FNON
WY - 07

Type D - left elevation




3 bdrm - front elevation





3 bdrm - right elevation

3 bdrm - left elevation



Clubhouse elevation



Clubhouse side I elevation



Clubhouse side 2 elevation

December 22, 2021 Revised January 12, 2022

Traffic Impact Study

Aparlments
Old Preston Highway (KY 6304)
Louisville, KY

Prepared for

Louisville Metro Planning Commission Kentucky Transportation Cabinet







Level of Service remains unchanged after build

Table 2. Peak Hour Level of Service

	A.M.			P.M.		
Approach	2021	2024	2024	2021	2024	2024
	Existing	No Build	Build	Existing	No Build	Build
Old Preston at Maple Spring Drive						
Maple Spring Drive Westbound	A	A	A	A	A	A
	8.7	8.7	8.8	8.8	8.8	9.1
Old Preston Southbound	A	A	A	A	A	A
	7.2	7.2	7.3	7.2	7.2	7.3
Old Preston at Entrance						
Entrance Eastbound			A 8.8			A 8.9
Old Preston Northbound (left)			A 7.3			A 7.4
Preston Highway at Cooper Chapel Road	C	C	C	D	D	D
	29.6	29.2	29.5	43.6	36.6	36.6
Commerce Crossings Eastbound	E	E	E	E	E	E
	59.2	56.0	56.4	77.6	77.5	77.5
Cooper Chapel Road Westbound	D	D	D	E	E	E
	43.1	41.2	42.3	60.3	60.3	60.5
Preston Highway Northbound	C	C	C	D	C	C
	25.6	25.3	25.4	52.7	25.6	25.9
Preston Highway Southbound	C	C	C	C	C	C
	25.5	25.4	25.5	29.1	29.4	29.2
Preston Highway at Interchange Drive	A	C	C	B	D	D
	7.4	25.8	28.7	19.3	39.5	40.4
Interchange Drive Eastbound	E	E	E	E	E	E
	72.6	74.8	74.1	75.0	74.5	75.4
Entrance Westbound	F	F	E	F	E	E
	87.9	68.2	68.2	84.8	79.1	79.1
Preston Highway Northbound	A	B	C	A	C	C
	4.1	17.5	21.2	8.8	30.1	30.6
Preston Highway Southbound	A	C	C	B	D	D
	5.9	22.6	23.8	19.2	36.4	37.4

Key: Level of Service, Delay in seconds per vehicle




Figure 8. 2025 Build Peak Hour Volumes





Figure 8. 2025 Build Peak Hour Volumes

Commerce Crossing Intersection AM



Commerce & Old Preston 1/11/2022-7:38am As light turns green

Commerce & Old Preston 1/11/2022-7:38am Green light




Commerce & Old Preston 1/11/2022-7:38am Red light


Commerce Crossing Intersection PM



Commerce & Old Preston 1/11/2022-5:10 pm Just turned green

Commerce & Old Preston 1/11/2022-5:11 pm Just turned red








Figure 8. 2025 Build Peak Hour Volumes

Interchange Intersection AM



Interchange & Old Preston 1/11/2022-7:45 am Green light

Interchange & Old Preston 1/11/2022-7:45am Red light

Interchange Intersection PM



Interchange & Old Preston 1/11/2022- 4:39 pm Red light

Interchange & Old Preston 1/11/2022- 4:40 pm Green light