


# Orientation Plan




Exterior Views



Existing Street View at  
Main Entrance

**A** View from Glenmary Ave at Main Entrance - New Landscaping & Accessible Bluestone Patio

# Exterior Views



Proposed Landscape Improvements

Louisville Collegiate School

REV 9-2-2015

omr architects, inc.

Exterior Views



**B** View from Glenmary Ave - California Driveway to Remain with New Grass Pavers



Existing Street View

Exterior Views



D1 View from Ray Ave



Existing Building Site



D2 View from Parking - Service Gate to Block Views to Service Area

## Exterior Views

Existing Pergola at Ray Ave Street Edge  
(Dumpsters to be relocated)



**E** View from Ray Ave - New Gate & Wall to Match Existing Entrance/Pergola

**Additional Site Features**



**Gate at Service Area**

Description: Aluminum slatted fence, to screen the service area on the south side of the Dining / Arts building. Refer to exterior renderings.



**Bluestone at Main Entrance**

Description: Bluestone pavers at Main Entrance, which, in conjunction with new landscaping, replaces the existing concrete and portion of the existing asphalt. Refer to exterior renderings.