

Landmarks Certificate of Appropriateness & Overlay District Permit Louisville Metro Planning & Design Services

EFFRSON COUNTY	Case No.:	8001	AIOOLO	Intake	Staff:	JH		
130N CO	Date: \	18/1	8	Fee.		\	-	
	Duic.	10/1			/			
Instructions: For detailed definitions application. Applications are to be made directly	s for <i>Signage</i>	are no lor	nger submitted	<i>Overlay Dist</i> I to Planning	rict Permit & Design	, please see Services. Ap	page 4 of	this for Signage
Project Information	<u>n</u> :			/				
Certificate of Appropri	<i>riateness</i> :	☐ Butche	ertown 🗹	Clifton 🗆	Cherokee	Triangle	□ Individu	ıal Landmark
		☐ Limerio	ck 🗆 Old L	ouisville [☐ Parkland	d Business	□ Wes	t Main Street
<u>Overlay Permit</u> : ☐ I	Bardstown/B	Baxter Ave	Overlay (BR	O) 🗆 Dow	ntown Dev	velopment F	Review Ove	erlay (DDRO)
	Nulu Review	Overlay I	District (NRO	D)		ाव	ecei	
Project Name:						<u> </u>	<u> </u>	
Project Address / Pard	cel ID:	17:37	Payne	Street			'.IAN 18	
Deed Book(s) / Page	Numbers ² :	Decd	Book	11001.	Page.	294 PLAN	ining & Desi	AN SERVICES
Total Acres:	·			,	, , , ,			
Project Cost:			PVA Ass	essed Value	ə:			
Existing Square Feet:		New Co	nstruction S	quare Feet:		Height (ft.):	Stories:
Project Description (us			<u> </u>					
			HAT	15	UL	SAF	E 7	-0
000	UP9	•						
						18	COA	1005

Contact Information:

Owner:	et Applicant: Check if primary contact
Name: MARK LEWIS	Name:
Company: ADVA CO BUSINESS	Company:
Address: 2908 Browsbono N	
City: LoV State: Zip: 40	206 City: State: Zip:
Primary Phone: 502 807 63	
Alternate Phone:	Alternate Phone:
Email: MLEWIS@ ABSITHE	Email:
Owner Signature (required):	2 .
Attorney: Check if primary contact	
Name:	Name:
Company:	
Address:	
City: State: Zip:	
Primary Phone:	Primary Phone:
Alternate Phone:	Alternate Phone:18 2018
Email:	Email: PLANNING & DESIGN SERVICES
	LT-VINING & DEDIGIA SEVAICES
	st be submitted with any application in which the owner(s) of the on, partnership, association, trustee, etc., or if someone other than the
I, MARIC CENIS, in	my capacity as MEMBER, hereby representative/authorized agent/other
certify that $\frac{R \sim S}{\text{name of LLC / corporation / partnership / ass}}$	is (are) the owner(s) of the property which ociation / etc.
is the subject of this application and that I am aut	horized to sign this application on behalf of the owner(s).
Signature:	Date: 1 - (2 - 18
I understand that knowingly providing false information on this a	pplication may result in any action taken hereon being declared null and knowingly making a material false statement, or otherwise providing false
Total Control of the	1 8 COA 1006

Please submit the completed application along with the following items:

Pro	ject information					
	Land Development Report ¹					
	Current photographs showing building front, specific project area, and surrounding buildings					
9	Pictures, samples, brochures, or other technical data describing materials, such as windows, doors, roofing, fencing, etc. to be used in the renovation or replacement					
	One map of the project area and surrounding properties (may be obtained from http://www.lojic.org/using the LOJIC Online Map)					
Site	e plan (see site plan example on next page)					
	Two sets of <u>site plans</u> drawn to scale with dimensions, as applies to the project, indicating property lines, structures, landscaping, fencing, and parking					
	Two copies of floor plans drawn to scale with dimensions and each room labeled					
	Two copies of <u>elevation drawings</u> (a drawing showing exterior walls) <i>drawn to scale</i> with dimensions. For fencing, only photos/drawings of the proposed fence are required.					
Cor by s	mmittee Review Only mmittee reviews may be required due to the complexity of the case. The necessity of these items will be determined staff upon review. Projects requiring committee level review include construction of new buildings, demolition, and jects that vary widely from design guidelines.					
	Two sets of 11"x17" format site plans drawn to scale with dimensions					
	Two sets of 11"x17" elevation drawings to scale with dimensions					
	Two sets of 11"x17" landscaping drawings to scale with dimensions					
	One set of mailing label sheets for: 1 st tier Adjoining Property Owners (APOs) ³ , owners, applicants, contacts, and Case Manager. Applicant is responsible for mailing.					
	One copy of the mailing label sheets					
	IAN 18 2018					
<u>Re</u>	sources: PLANNING & DESIGN SERVICES					
1.	Detailed instructions to obtain a Land Development Report are available online at: http://ags2.lojic.org/lojiconline/					
2.	Deeds and plats can be found at the Jefferson County Clerk's Office, located at the 2 nd floor of Metro Hall (527 West Jefferson Street, telephone: 502-574-6220). Many deeds, plats and other records are available online at: http://www.landrecords.jcc.ky.gov/records/S0Search.html					
3.	Adjoining property ownership information can be found at the Property Valuation Administrator (PVA) office at 531 Court Place, Suite 504 or via their website: https://jeffersonpva.ky.gov/					
4.	View agency comments at: http://portal.louisvilleky.gov/codesandregs/mainsearch . Enter your case number in the 'Permit/Case/Docket Number' search bar and then select your case under the 'Application Number' tab.					
	n g COA 1006					

STRUCTURAL SERVICES, INC.

5948 Timber Ridge Dr., Suite 201, Prospect, KY 40059 Telephone: (502) 292-2100 www.structural-services.com

January 8, 2018

Mr. Mark Lewis 1737 Payne St. Louisville, KY 40206

Re: Structural Review

1737 Payne St.

Louisville, KY 40206

BECEIVED

LIAN 18 2013

PLANNING & DESIGN SERVICES

Dear Mr. Lewis:

Per your request on December 21st, 2017 the above noted residence was visited to review the condition of the existing structure. The residence is a one story ranch with a basement. The basement walls consist of stone and brick masonry with a dirt floor. The structure of the house consisted of traditional dimensional wood framing.

Upon review the main level floor structure was severely out of level in several areas of the house. This was due to the deteriorated condition of the framing. Upon entering the basement the moisture levels were extremely high. The floor framing was moist to the touch. In several areas there was damage due to the past presence of termites. There were several locations where steel posts were added to shore the existing structure. It should be noted that most of the attempted repairs do not meet Kentucky Building Code requirements.

It appears that water infiltration at the joint between the basement wall and floor structure has caused the floor framing to rot and settle. There was one location where an attempt to repair it was made but the problem has progressed to other locations.

While the majority of wall and roof framing was not visible during our inspection is should be noted that there was evidence of water infiltration as seen in the water staining in ceiling. Roof framing located above the side door was not framed in accordance with current building codes and showed signs of disrepair. With the evidence of termites in the floor framing it should be noted that there is a good possibility of other hidden areas of termite damage.

Based on the above it is our opinion that the residence is not safe to occupy.

If you have any questions concerning the above please do not hesitate to call. We appreciate the opportunity to work with you.

Regards

Nicholas D. Carter P.E.

NICHOLAS D.
CARTER
25710


CENSE

STONAL


5105 8 1 MAI.

SECEINED

Rear Elevation of Building



Front Elevation of Building





Water staining and damage to existing ceiling.



Side door porch roof framing.

.JAN 18 2018



Termite damage in existing floor framing.




Steel posts placed to shore the existing floor framing.



IAM 1 8 2018

PI ANNING & DESIGN SERVICES





.MN 182013

PLANNING & DESIGN SERVICES