



Historic Landmarks and Preservation Districts Commission

Report to the Committee

To: Clifton Architectural Review Committee
Thru: Cynthia Elmore, Historic Preservation Officer *CE*
From: Savannah Darr, Historic Preservation Specialist
Date: February 23, 2018

Case No: 18COA1021
Classification: Committee Review

GENERAL INFORMATION

Property Address: 146 Coral Court

Applicant: George Hanratty
1 Angora Court
Louisville, KY 40206
502-445-6269
geohanratty@gmail.com

Owner: Kathleen Hanratty
146 Coral Court
Louisville, KY 40206
502-523-8218
kate.hanratty@gmail.com

Estimated Project Cost: \$8,500

Description of proposed exterior alteration:

The applicant seeks approval to replace 13 double hung wood windows on all facades of the house. Three second story windows on the front façade are historic 1/1 double hung wood windows. The applicant proposes to replace those with 1/1 double hung wood windows made by Jeld Wen. The remaining 10 windows proposed for replacement are on the side and rear elevations, which are 1/1 double hung wood replacement windows. The applicant proposes to replace those with 1/1 double hung vinyl windows made by ProVia. All other windows on the front façade of the house will remain.

Communications with Applicant, Completion of Application

The application was received on February 6, 2018 and considered complete and requiring committee level review on February 12, 2018. The case is scheduled to

be heard by the Clifton Architectural Review Committee (ARC) on February 28, 2018 at 5:30 pm, at 444 S. 5th Street, Conference Room 101.

FINDINGS

Guidelines

The following design review guidelines, approved for the Clifton Preservation District, are applicable to the proposed exterior alteration: **Windows**. The report of the Commission Staff's findings of fact and conclusions with respect to these guidelines is attached to this report.

The following additional findings are incorporated in this report:

Site Context/ Background

The property is located on the west side of Coral Court three lots north of Coral Avenue. It is zoned R5A within the Traditional Neighborhood Form District. The site contains the two-and-a-half-story American Foursquare house, and is bound by an alley to the west, similar houses to the north and south, and Coral Court and Bingham Park to the east.

There are no previous COAs for this property.

Conclusions

The proposed window replacement generally meets the Clifton design guidelines for **Windows**. The side and rear elevations already have replacement wood windows. The applicant proposes new vinyl windows to match. Three second story windows on the front façade are historic 1/1 double hung wood windows. From the exterior, staff could not determine the condition of these windows. Due to the significant elevation of the house, only the upper sashes of the windows were visible and they had storm windows on top. This significant elevation makes the windows only fully visible from the sidewalk area. Furthermore, the applicant proposes to replace those with 1/1 double hung wood windows made by Jeld Wen. Based on these factors, staff recommends approval of this COA application.


RECOMMENDATION

On the basis of the information furnished by the applicant, staff recommends the application for a Certificate of Appropriateness be **approved with the following conditions**:

1. **The new windows shall fit the historic window openings.**
2. **If the design or materials change, the applicant shall contact staff for review and approval.**

The foregoing information is hereby incorporated in the Certificate of Appropriateness as approved and is binding upon the applicant, his successors, heirs or assigns. This Certificate does not relieve the applicant of responsibility for obtaining the necessary permits and approvals required by other governing agencies or authorities.

2/23/18
Date


Savannah Darr
Historic Preservation Specialist

Windows

Clifton Design Guideline Checklist

+ Meets Guidelines
- Does Not Meet Guidelines
+/- Meets Guidelines with Conditions

NA Not Applicable
NSI Not Sufficient Information

	Guideline	Finding	Comment
W1	The maintenance and repair of historic windows are essential to preserving the historic character and fabric of Clifton structures and the overall Clifton historic district. For that reason, historic windows on street-address façades and street-facing façades shall not be replaced with new windows unless the Clifton ARC determines that the condition of existing windows, safety or energy efficiency considerations, or other relevant factors support window replacement. During the planning stage for possible window replacement on any façade, and prior to submittal of an application for a Certificate of Appropriateness for window replacement, property owners should consult with the Landmarks staff on the application of these guidelines to their structure, options for addressing the property owner's needs, and concerns regarding their windows.	+/-	Three second story windows on the front façade are historic 1/1 double hung wood windows. The applicant proposes to replace those with 1/1 double hung wood windows made by Jeld Wen (see conclusions)
W2	If historic windows on façades other than street-address façades or street-facing façades are replaced, or the owner is authorized to replace windows on street-address façade or street-facing façade pursuant to W1, the new windows shall convey the same visual appearance as the historic windows. The visual appearance of a window is based on details such as sash dimension, muntin configuration, reveal depths, glass-to-frame ratios, glazing patterns, frame dimensions, trim profiles, and other decorative features. Replacement windows may either be accurate reproductions using historical, pictorial, and physical documentation or be a new design that is compatible with the historic character of the building and the district. Use of wood, metal, or synthetic window systems for authorized window replacement is permissible. During the planning stage for possible window replacement on any façade, and prior to submittal of an application for a Certificate of Appropriateness for window replacement, property owners should consult with the Landmarks staff on the application of these guidelines to their structure, options for addressing the property owner's needs, and concerns regarding their windows.	+/-	The side and rear elevations already have replacement wood windows. New vinyl windows are proposed to match.
W3	Replacement sash should not be used that does not fit historic window openings. Original openings should never be blocked-in to accommodate stock-sized windows.	+	
W4	Replacement windows proposed for façades other than street-address façades or street-facing façades, and those authorized pursuant to W1 for street-address façades and	+	Double hung windows being replaced with double hung windows

	Guideline	Finding	Comment
	street-facing façades, shall operate in the same way as the original windows - double-hung windows are replaced with double hung, and casement windows are replaced with casements.		
W5	Thermal glazing windows that have muntins in accordance with W2 shall have such muntins permanently applied and may also incorporate internal dividers between the glass panes.	NA	No muntins
W6	Reflective or insulating film shall not be applied to window glass on street-address façades or street-facing façades.	+	
W7	Smoked, tinted, or reflective glass shall not be used on windows on street-address façades or street-facing façades.	+	
W8	Transoms or sidelights shall not be blocked-in or back-painted.	NA	
W9	The number, size, location, or shape of original windows shall not be altered on street-address façades or street-facing façades by making new window openings or permanently blocking existing openings. If windows are no longer needed, they should be shuttered if original shutters exist. If shutters do not exist, a temporary closure should be prepared, leaving the window frame intact.	NA	
W10	Any new window openings for a new use shall not be located on street-address façades or street-facing façades.	NA	
W11	The front face of historic window trim shall not be covered with metal or siding material. Siding may butt up to the side of historic window trim.		
W12	New floors or dropped ceilings shall not be installed that block the glazed area of windows. If such an approach is required, the design should incorporate setbacks that allow the full height of the window to be seen unobstructed.	NA	
W13	If exterior storm windows are installed they should duplicate the shape of the original window.	NA	
W14	When installing exterior storm windows or screens do not damage or obscure historic windows or frames.	NA	
W15	Window sashes shall not be altered to accommodate window air-conditioning units.	NA	
W16	When installing security bars do not obscure the architectural character of original windows or damage historic fabric. Commercial security grills should retract out of sight during business hours.	NA	
W17	Awnings shall be designed to complement existing architectural features. They should not overwhelm the façade.	NA	
W18	Awnings shall be of a material and form compatible with the building's historic character. Contemporary designs may be considered if compatible with the design and character of the building.	NA	
W19	Awnings shall be installed in a way that does not harm the building. Limit hardware installation to that which is required for structural stability. Anchors shall be installed in mortar joints, not masonry units.	NA	
W20	On commercial buildings attach awnings between the window display area and the signboard or second-floor window sills. Awnings shall be attached below the transom line where historic prism glass is present and building scale allows.	NA	
W21	Awnings shall be installed so that the valance is no lower than permissible by code (Building Code or Public Works).	NA	
W22	Replacement shutters should match the visual appearance, size, and location of the originals and may be constructed of wood, metal, or synthetic material.	NA	
W23	Shutters shall be installed only where there is historic evidence for them.	NA	