DESIGNED FOR YOU. ENGINEERED FOR SUCCESS.



5151 JEFFERSON BLVD. LOUISVILLE, KY 40219 PHONE: (502) 485-1508 FAX: (502) 485-1606

TRANSMITTAL FORM

IVI	IND	LSCC	, , ,	www.MindelScott.com	DATE	July 27, 2021		REF.# 3805	
					RE:	Old Preston H	Iwy Apartm	ients	
TO o To Whom It May Concern						Karst Survey Report			
	OLLOWING SINTS	G ITEMS ARE	: X A	TTACHED SHIPPED UNDER SEP ORIGINALS		ER VIA SAMPLES		BASE MAPS	
	YLARS			COPIES		CHANGE ORDERS		CONTACT PRINTS	
	DCUMENT:	c c		COMPACT DISCS		FIELD DATA		PHOTO ENLARGEMI	ENTS
	ECIFICATI			SHOP DRAWINGS		ILLD DATA		FHOTO ENLARGEME	ENIS
ITEM QUANT. DATE SUBMITTAL						DESCRIPTION			DISP.
			NUMBER	W (C P (A)		D-SCRIPTION			
1	1	07/27/21	1	Karst Survey Report (below)					2,4
2	1	07/27/21	1	KGS Karst Potential Map					
3	1	07/27/21	1	Aerial Site / Feature Location Map					
4	1	07/27/21	1	LOJIC Map					2,4
		-	-						
	E DISPOSIT APPROVA	TION OF EACH	I ITEM IS AS F	OLLOWS: 7-APPROVED AS SUBMITTED			13- BORROWE	D ITEMS RETURNED	
	YOUR USI			8-APPROVED AS NOTED			14- RETURN B		
		comment.		9-REVISE & RESUBMIT			15		
		ATE ACTION		10-REJECTED			16		
	SIGNATUI EQUESTEI	RE & RETURN D		11-NO EXCEPTIONS TAKEN 12-NOTE MARKINGS			17-		
0-A5 K	LQUE31E	<u>u</u>		12-NOTE WARRINGS			10-		
REMA			_	al engineer, Travis Brown, conducted			_		
	-			ne characterizes the site as having into					
				ate project vicinity. The engineer visit		-			
				nfirmed the presence of sinkholes on					
			•	ely to encounter karst formations and				• •	
				ave a geotechnical consultant perforn			•	•	
po	ssible pri	or to constru	ction. And it	is recommended their services be ret	tained durin	g construction to c	all if/when sin	nkholes are encountered. Care	e
she	ould be ta	ken during e	arthwork to	investigate and properly remediate p	otential sink	holes, per the geot	echnical engi	neer's recommendations. It wi	ill
be	mportan	t to proofroll	thoroughly	before placingfill and after cutting.					
COPIE	S TO:					Thank y	ou, C)	
	_				SEN	TBY:	5/mm	/	
						Travic A	Brown Pl	F.	





