

**INITIAL / RE-INSPECTION / BOND RELEASE FORM**

DATE: 6-23-23

PROJECT NAME: 2038 Tyler Ln

SECTION/STREET: \_\_\_\_\_

REQUESTED BY: Kevin Sullivan 502-562-9200

COMMENTS: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

UNDEVELOPED LOTS = \_\_\_\_\_

RELEASE OF BOND: YES \_\_\_\_\_ NO \_\_\_\_\_

**INSPECTOR'S COMMENTS:**

The grate to the catch basin located in the parking pad is at a higher elevation than the surrounding pavement preventing water to enter. Previously, a swell was present in the concrete section of the pad collecting water from roadway and directing to the pipe. Presently, water is draining to the rear of the property. Drainage will need to be corrected and returned to previous condition.

INSPECTOR'S SIGNATURE: [Signature] DATE: 6/26/23