Variance Justification:

In order to justify approval of any variance, the Board of Zoning Adjustment considers the following criteria. Please answer <u>all</u> of the following items. Use additional sheets if needed. <u>A response of yes, no, or N/A is not acceptable</u>.

1. Explain how the variance will not adversely affect the public health, safety or welfare.

IT IS WITHIN THE PROPERTY BOUNDRIES, AND WILL BE BUILT TO ALL SAFE BUILDING CODES. INCLUDING A 2 HOUR FIRE RATED WALL ON EITHER SIDE OF ADDITION FACE NEIGHBURING PROPERTIES

2. Explain how the variance will not alter the essential character of the general vicinity.

IT IS WITHIN THE PROPERTY BOUNDRIES, IT IS IN THE BACK YARD OF THE PROPERTY, NOT IN SIGHT FROM FRONT UR REAR STREETS. IT WILL BE FINISHED IN A ESTHICLY ATTRACTIVE EXTERIOR

3. Explain how the variance will not cause a hazard or a nuisance to the public.

IT IS WITHIN THE PROPERTY BOUNDAIES IN THE MIDDLE OF THE PROTERTY WITH NO ACCESS TO THE GENERAL PUBLIC

4. Explain how the variance will not allow an unreasonable circumvention of the requirements of the zoning regulations.

IT WILL BE BUILT IN THE FOOTPRINT OF THE EXISTING BOCK PORCH ON THE ZND FLOOR HECEIVED

SEP 23 2019

Additional consideration:

PLANNING &

1. Explain how the variance arises from special circumstances, which do not generally apply to CES land in the general vicinity (please specify/identify).

THE BUTILE PROPERTY IS IN VIOLATION TO THIS REGULATION AS PHE PROPERTY WAS DEVELOPED IN THE 1940'S

Explain how the strict application of the provisions of the regulation would deprive the applicant of the reasonable use of the land or would create unnecessary hardship.

THE HOUSE WAS BUILT WITH I BATHROOM THAT MEDSURES

3'-O" X 7'O" ALMOST NUT FUNCTIONAL BY TODAYS STANDARDS

THE BED ROOM IS LOCATED ON THE ZND FLOOR WITH NO BATH

FACILITIES

3. Are the circumstances the result of actions of the applicant taken subsequent to the adoption of the regulation from which relief is sought?

YES, APTER RECENTLY PURCHASING THE HOME THE PRESENT BATH FACILITIES WERE PISCUVERED TO BE NON FUNCTIONAL

1 9 - WARMANCE - 0 0 5 2