

1. Historic Name(s) 103 W. Kentucky Street
 Original Owner _____
 2. Present Name 103 W. Kentucky Street
 3. Location 103 W. Kentucky Street

22. ADD/County JF 01516
 23. U.S.G.S. Quadrant (15'/75') West Louisville 0,7,9
 24. UTM Reference
16 608000 4229000
 Zone Easting Northing

4. Owner's Name _____


25. Coordinate Accuracy E

5. Owner's Address _____

26. Prehistoric Site _____ Object _____
 Historic Site _____ Structure _____
 Building X Other _____

6. Open to Public Yes _____ No X
 7. Visible from road Yes X No _____
 8. Ownership
 Private _____
 Local _____
 State _____
 Federal _____

27. National Register District Name:
Old Louisville 0,5,1



11. Architect _____
 12. Builder _____
 13. Date 1886 A. 5 B.
 14. Style
 A. Victorian 2
Vernacular
 B.
 15. Original Use single family residential 1
 16. Present use single family residential
 17. Condition good 2

28. Significance Evaluation
contributing element NR dist. h
 29. Status _____ Date _____
 National Landmark _____
 National Register X 1984
 Landmark Certificate _____
 Kentucky Survey _____
 Local Landmark _____
 HABS/HAER _____

18. Description
 This three story brick building has an ashlar masonry foundation and is two bays wide. The entry way is protected by a metal overhang (not original) which probably replaced a masonry porch. The entrance has two recessed doors (not original). On the left is a large window with wood framing above and below and topped with wood voussoirs. This framing
 (Continue on Back) (over)

No. Stories 3 D
 Single Pile _____ NA XX
 Double Pile _____
 Floor Plan _____ 0
 Structural Fabric brick A. C B.
 Decorative Fabric wood A. H
stone B. Q
 Roof Form gable

30. Historic Theme
 Primary architecture 013
 Secondary _____
 Other _____
 31. Endangered Yes _____ No X
 32. Preservation Project Status _____
 Actual Cost in \$1,000s _____

19. History
 This building was first occupied in 1886 by Samuel Hartwell, Jr., a medical doctor.

33. ATTACH PHOTO

 Roll No. 155
 Picture No. 18
 Direction _____
 34. Prepared by
Joanne Weeter
Researcher

This structure is typical of residences found in the Old Louisville Preservation District. The building's oriel window, the lattice-work found in the gable of
 (over)

35. Organized in
Landmarks Commission E
March 20, 1984

Carson Annual Directories of the City of Louisville

RE: 8/8/96 (103 West Kentucky)

Post-it® Fax Note 7671 Date 8/8/96 # of pages 2
 To Bruce Duncan From Darnell
 Co./Dept. _____ Co. _____
 Phone # 585-5434 Phone # 574-3501
 Fax # 561-0726 Fax # _____

18. was probably added to reduce the size of the original window that is now boarded. The second floor has a one-over-one window on the right with a rectangle of board and batten below and stone voussoirs above. To the left is an oriel window with four one-over-one lights and an art glass transom which has been aluminum sided. The third floor has a small, square casement window on the right and a four-over-four window on the left, flanked by two long narrow two-over-two windows. This window doesn't reach full height and is surmounted by a wide arch with brick voussoirs. A brick stringcourse cuts through the left bay of the third floor and is surmounted by a gable with lattice-work in its peak. An eyebrow vent is visible on the right side of the building's roof.
20. the third floor and the eyebrow vent on the building's roof give this building a unique character.