



Image 1: Litter and debris along western boundary behind dumpsters of strip mall.



Image 2: Trash and debris in interior of easement near northern boundary.



Image 3: Litter and debris along western boundary behind dumpsters of strip mall.



Image 4: Litter and debris along western boundary behind dumpsters of strip mall.



Image 5: Litter and debris in NW corner of easement. Large plastic pallet was present during the 2025 visit.



Image 6: Litter and debris in NW corner of easement. Sofa was present during the 2025 visit.