### **INFRASTRUCTURE IMPROVEMENTS—Plaza Concrete**



### **INFRASTRUCTURE IMPROVEMENTS Continued**





Hospital Dock



Hillside Gazebo Sink Area



Settling Basin



#### **INFRASTRUCTURE IMPROVEMENTS Continued— Doors**



**Islands Public Doors** 



**Islands Service Entry** 






Maned Wolf Door—corrosion at bottom

### **GUEST EXPERIENCE IMPROVEMENTS**








(Admin Building—formerly dark blue carpet)





# RIDES & ATTRACTIONS—Splash Park








Splash Park Pad







## **RIDES & ATTRACTIONS—Splash Park Continued**





Broken Apparatus







Splash Canopy

## RIDES & ATTRACTIONS—Carousel

#### **Carousel Deck**









Carousel Rounding Board—paint peeling





# RIDES & ATTRACTIONS—Train Canopies



