






## PLANNING & DESIGN SERVICES

COMM A7430	DRAWN M.W.O.	IN HSE M.L.Y.	DATE 03/19/18
---------------	-----------------	------------------	------------------

NOT FOR CONSTRUCTION

KEYNOTES - EXISTING BUILDINGS ○

1. PAINTED 8 x 8 SCORED CMU - NON HISTORIC
2. PRECAST CONCRETE WALL CAP - NON HISTORIC
3. METAL DOCK DOOR
4. ANGLE IRON JAMB PROTECTION
5. DETERIORATED PAINTED 8 x 8 SCORED CMU - NON HISTORIC
6. PAINTED FACE BRICK WALL
7. PAINTED FACE BRICK PLASTER
8. LIMESTONE PLASTER CAP
9. DETERIORATING WOOD STEPS - NON HISTORIC
10. CLAY TILE WALL CAP
11. POURED IN PLACE CONCRETE LOADING DOOR - NON HISTORIC
12. METAL ROLL - UP DOCK DOOR - NON HISTORIC
13. STEEL BEAMS - NON HISTORIC
14. REFRIGERATION EQUIPMENT AND ENCLOSURE - NON HISTORIC
15. METAL GUTTER
16. VINYL DOWNSPUT - NON HISTORIC
17. PAINTED LIMESTONE WALL CAP
18. GLAZED PATTERNED BRICK
19. LIMESTONE PATTERNED CORNERS
20. GLASS BLOCK INFILL
21. GLAZED BRICK
22. LIMESTONE SILL
23. METAL (ALUMINUM) SLOPED ROOF - NON HISTORIC
24. SPLIT FACED CMU NON - HISTORIC
25. STEEL BEAM
26. ALUMINUM REPLACEMENT WINDOW FRAME AND GLASS
27. LIMESTONE KEY
28. GLAZED BRICK FAN
29. ALUMINUM REPLACEMENT WINDOW FRAME - NON HISTORIC
30. ALUMINUM REPLACEMENT WINDOW FRAME (FULL GLASS) - NON HISTORIC
31. BRICK QUOIN PATTERN
32. BRICK WALL CAP NON - HISTORIC
33. PAINTED FACE BRICK INFILL WALL - NON HISTORIC
34. METAL IDENTIFICATION SIGN - NON HISTORIC, ORIGINAL SIGNAGE
35. ROOFING CMU WALL - NON HISTORIC
36. PARTIALLY REMOVED BRICK WALL STRUCTURE
37. METAL WALL CAP - NON HISTORIC
38. CMU INFILL, PARGED AND PAINTED - NON HISTORIC
39. METAL CANOPY FRAME
40. METAL CANOPY FRAME
41. AREAS OF FACE BRICK DETERIORATION
42. ANGLE IRON SURROUND PROTECTION
43. PAINTED CMU WALL - NON HISTORIC
44. ROOFING CMU WALL - NON HISTORIC
45. SLIDING METAL DOOR, SINGLE
46. SLIDING METAL DOOR, BI-PARTING
47. WOOD FRAME CANOPY - NON HISTORIC
48. BAY WINDOW - NON HISTORIC
49. CANTILEVERED CANOPY - NON HISTORIC
50. SUSPENDED METAL CANOPY - NON HISTORIC
51. CONCRETE LOADING DOCK WITH CRAWLWAY BELOW
52. ELECTRICAL PANELS - NON HISTORIC
53. STEEL BEAM HAUNCH
54. BRICK SILL, PAINTED
55. EXISTING MASONRY OPENING



PRELIMINARY

SHEET	I201	<h1>JOSEPH &amp; JOSEPH</h1> <p>ARCHITECTS SINCE 1908</p>	<p>500 S. 4TH STREET LOUISVILLE, KY. 40202 V. 502.583.8888 F. 502.583.8414 <a href="http://www.josephandjoseph.net">www.josephandjoseph.net</a></p>
SET			

## ABUILDING "A"AL

EAST & WEST  
ELEVATIONS

**GROCCERS ICE**

Level 1	
00' - 0"	
Level Entry	
97' - 0"	
Level Street	
96' - 5"	


---

WEST  
TIONSEAST &  
FIFVAT

1

FEET	
10202	
8	

550 S. 4TH STREET  
LOUISVILLE, KY. 40202  
V. 502.583.8888

# EPH

JOSEPH &amp; ARCHIT

	SHEET	H201
--	-------	------



9/28/2018 11:47:07 AM

9/28/2018 11:47:07 AM  
18 COA 1 2 4 7



# KEYNOTES - EXISTING BUILDINGS ○

1. PAINTED 8 x 8 SCORED CMU - NON HISTORIC
2. PRECAST CONCRETE WALL CAP - NON HISTORIC
3. METAL DOCK DOOR
4. ANGLE IRON JAMB PROTECTION
5. DETERIORATED PAINTED 8 x 8 SCORED CMU - NON HISTORIC
6. PAINTED FACE BRICK WALL
7. PAINTED FACE BRICK PILASTER
8. LIMESTONE PILASTER CAP
9. DETERIORATING WOOD STEPS - NON HISTORIC
10. CLAY TILE WALL CAP
11. POURED IN PLACE CONCRETE LOADING DOOR - NON HISTORIC
12. METAL ROLL - UP DOCK DOOR - NON HISTORIC
13. STEEL BEAMS - NON HISTORIC
14. REFRIGERATION EQUIPMENT AND ENCLOSURE - NON HISTORIC
15. METAL GUTTER
16. VINYL DOWNSPOUT - NON HISTORIC
17. PAINTED LIMESTONE WALL CAP
18. GLAZED PATTERNED BRICK
19. LIMESTONE PATTERNED CORNERS
20. GLASS BLOCK INFILL
21. GLAZED BRICK
22. LIMESTONE SILL
23. METAL (ALUMINUM) SLOPED ROOF - NON HISTORIC
24. SPLIT FACED CMU - NON HISTORIC
25. STEEL BEAM
26. ALUMINUM REPLACEMENT WINDOW FRAME AND GLASS
27. LIMESTONE KEY
28. GLAZED BRICK FAN
29. ALUMINUM REPLACEMENT WINDOW FRAME - NON HISTORIC
30. ALUMINUM DOOR AND FRAME (FULL GLASS) - NON HISTORIC
31. BRICK QUIN PATTERN
32. BRICK WALL CAP - NON HISTORIC
33. PAINTED FACE BRICK INFILL WALL - NON HISTORIC
34. METAL IDENTIFICATION SIGN - NON HISTORIC, ORIGINAL SIGNAGE WAS LIMESTONE
35. ROOFING MATERIAL - NON HISTORIC
36. PARTIALLY REMOVED BRICK WALL STRUCTURE
37. METAL WALL CAP - NON HISTORIC
38. CMU INFILL, PARGED AND PAINTED - NON HISTORIC
39. METAL CANOPY ROOF
40. METAL CANOPY FRAME
41. AREAS OF FACE BRICK DETERIORATION
42. ANGLE IRON SURROUND PROTECTION
43. PAINTED CMU WALL - NON HISTORIC
44. PAINTED CMU WALL, DETERIORATED - NON HISTORIC
45. SLIDING METAL DOOR, SINGLE
46. SLIDING METAL DOOR, BI-PARTING
47. WOOD FRAME CANOPY - NON HISTORIC
48. BAY WINDOW - NON HISTORIC
49. CANTILEVERED CANOPY - NON HISTORIC
50. SUSPENDED METAL CANOPY - NON HISTORIC
51. CONCRETE LOADING DOCK WITH CRAWLWAY BELOW
52. ELECTRICAL PANELS - NON HISTORIC
53. STEEL BEAM HAUNCH
54. BRICK SILL, PAINTED
55. EXISTING MASONRY OPENING



RECEIVED  
SEP 28 2018  
PLANNING &  
DESIGN SERVICES

REVISIONS				
NO.	DESCRIPTION	DATE	BY	CHKD.

NOT FOR CONSTRUCTION

GROCKERS ICE  
MAIN ST  
DE DEVELOPMENT LLC

NORTH & SOUTH  
ELEVATIONS  
HISTORIC  
ABUILDING "A"AL

500 S. 4TH STREET  
LOUISVILLE, KY 40202  
ARCHITECTS SINCE 1908  
V. 502.583.8888  
F. 502.583.8414  
www.josephandjoseph.net  
© 2018 C. Joseph & Joseph, Creative & Historic IV Architects

9/28/2018 11:47:16 AM

PRELIMINARY

SHEET  
H202  
SET

18 COA 1247





## PLANNING & DESIGN SERVICES



NOT FOR CONSTRUCTION



## DESIGN SERVICES



DF DEVELOPMENT LLC

COMM A7430	DRAWN M.W.O.	IN HSE M.L.Y.	DATE
---------------	-----------------	------------------	------

NOT FOR CONSTRUCTION